



Photograph 1: View of Castaic Creek, facing south (downstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: May 18, 2018



Photograph 2: View of Castaic Creek, facing north (upstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Nonnative and invasive tamarisk (Tamarix sp.) trees are the dominant plant in view. Photo date: May 18, 2018

Exhibit 5 – Page 2






Photograph 3: View of Castaic Creek, facing north (upstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: March 6, 2024



Photograph 4: View of Castaic Creek, facing north (upstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo taken from existing roadway at same general location as Photograph 2. Photo date: April 12, 2024

Exhibit 5 – Page 3



Photograph 5: View of Castaic Creek, facing northeast (upstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: April 12, 2024



Photograph 6: View of Castaic Creek, facing northwest (upstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: March 6, 2024







Photograph 7: View of Castaic Creek, facing south (downstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo taken from existing roadway at same general location as Photograph 1. Photo date: March 6, 2024



Photograph 8: View of Castaic Creek, facing south (downstream), at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: April 12, 2024

Exhibit 5 – Page 5

GLENN LUKOS ASSOCIATES





at proposed off-site Tapia Canyon Road Bridge improvement area. Photo date: March 6, 2024



Photograph 10: East-facing view of the existing Tapia Canyon Road crossing and downstream culverts. Photo date: May 24, 2024